

Sanitary Sewer Overflow 5-Day Follow Up Report

Division of Surface Water

	Division of surface water
Report Submitted By	
Date:	7/13/2015
Facility name:	Madison WWTP
Ohio NPDES permit no.:	3PK00032*MD
Period covered by report:	7/11/2015
Contact person	
Name:	Michael McGlothin
Title:	Superintendent
Mailing address:	7815 Cashen Road Madison, Ohio 44057
County:	Lake
Telephone:	(440)428 - 1794
Email:	Michael.mcglothin@lakecountyohio.gov
Signature required at end of form	
Overflow Information	
Event start date and time — if multiple locations, include information for each	7/11/2015 @ 8:53am
Event end date and time	7/11/2015 @ 4:23pm
Location(s) the SSO – include unique ID number of one exists	Force main. 3115 Center Road North Perry, Ohio
Destination(s) of overflow	\square Basement or building \boxtimes Ground \boxtimes Storm sewer to receiving water \square Directly to receiving water
Estimated volume (million gallons) - if multiple locations, include volume for each	.025 MGD spilled on the ground, then traveled approximately 30 yards before it entered a storm sewer and ultimately Lake Erie.
Sewer system component(s) from which release occurred	☐ Manhole ☐ Constructed overflow ☒ Pipe crack ☐ Pump station ☐ Other (explain) Force main.
Cause(s) of overflow	□ Extreme weather □ Equipment failure □ Power failure □ Debris in line □ Roots □ Grease □ Other blockages □ Line deterioration □ Vandalism □ Other (explain)

EPA 4237 (Rev. 6/14) Page 1 of 2